

## Attachment A - NSCC Comcast Physical Plant Audit Issues

	Address	City	Issue	Comments	Codes	
					NESC	NEC
1	1120 Amble Dr	AH	Drop not buried at pedestal		352	
2	1168 Karth Lake Dr	AH	Broken ground on drop at house			250
3	1190 Amble Dr	AH	Smashed pedestal	Drop smashed between base and cover	214	
4	1357 W Floral Dr	AH	Cable TV drop 15' 0" inches road		Table 232-1	
5	1357 W Floral Dr	AH	Drop tied to pole above power's secondary		235	
6	1357 W Floral Dr	AH	Hardline not properly attached to pole	Very messy, missing cable guard on pole	239D3	
7	1383 Arden View Dr	AH	Drop grounded to outside water faucet	Check grounds throughout this neighborhood. Many are connected to the outside water		820.100.B.2.(2)
8	1384 Arden View Dr	AH	Drop grounded to outside water faucet			820.100.B.2.(2)
9	1385 Arden View Dr	AH	Drop grounded to outside water faucet			820.100.B.2.(2)
10	1386 Arden View Dr	AH	Drop grounded to outside water faucet			820.100.B.2.(2)
11	1407 W Floral	AH	Drop not properly attached to pole		239D3	
12	1407 W Floral	AH	Ground wire not properly attached to pole		239A	
13	4228 Hamline Ave	AH	Drop not buried		352	
14	4235 Hamline Ave	AH	Drop touching power	Across Hamline Ave	235	
15	4436 Snelling Ave	AH	No bond to power's ground		92C3	
16	4765 Prior Ave N	AH	Cable hardline and phone are touching		235H	
17	N45 03.265 W093 09.918	AH	Power supply not locked		224B2c	
18	N45 03.535 W093 10.234	AH	Power supply fuse box not locked		224B2c	
19	N45 04.221 W093 09.450	AH	Power supply fuse box not locked		224B2c	
20	Snelling Ave & Highway 96	AH	Missing down guy		264	
21	1396 Idaho Ave	FH	Power supply not locked		224B2c	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
22 1488 Idaho Ave	FH	Drop and ground wires not properly attached to house		820.24 & 820.44	
23 1488 Idaho Ave	FH	No bond to power ground	At pole	92C3	
24 1495 Roselawn Ave	FH	Loose down guy		264	
25 1502 Idaho Ave	FH	No bond to power	At Pole	92C3	
26 1515 Coffman St	FH	Loose down guy	Missing guy across Hoyt Ave	264	
27 1522 Idaho Ave	FH	Hardline cable not attached to pole properly	Missing cable guard	239D3	
28 1525 Hollywood Ct	FH	Hardline cable not attached to pole properly		239D3	
29 1565 Hollywood Ct	FH	Cable not bonded to power and phone ground		99C	
30 1625 Hollywood Ct	FH	Missing down guy	Across Snelling Ave	264	
31 1649 Hollywood Ct	FH	Cable not bonded to power ground		99C	
32 1661 Coffman St	FH	Strand pulling out of clamp	Not a violation, Comcast should check		
33 1662 Hollywood Ct	FH	Cable not bonded to power ground		99C	
34 1893 Larpenteur Ave	FH	Power supply not locked		224B2c	
35 1914 Holton Ave	FH	Missing down guy	Going east	264	
36 111 Yorkton Ridge	LC	Smashed ped (snow plow hit in 2010-11 winter per resident)		214	
37 118 Demont Ave E	LC	Drop not properly attached to pole		239D3	
38 124 Canabury Ct	LC	Drop not buried		352	
39 127 Canabury Ct	LC	Drop not buried		352	
40 180 County Road B2	LC	Missing pedestal cover		214	
41 180 County Road B2	LC	Underground cable drop exposed above ground	All around Multiple Dwelling Unit	352	
42 186 Big Circle Dr	LC	Cables sticking out of ground, temp (RG11) running above ground		352	
43 191 Yorkton Ridge	LC	Ground not connected to hardline		92	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
44 210 County Road B2	LC	Underground cable drop exposed above ground	All around Multiple Dwelling Unit	352	
45 226 S Owasso Blvd E	LC	Loose down guy	Sharp end of guy wire not secured	264	
46 227 County Road B2	LC	Hardline cable not attached to pole properly		239D3	
47 227 County Road B2	LC	Power supply not grounded		92	
48 231 Demont Ave E	LC	Drop not properly attached to pole	Abandoned?	239D3	
49 2811 Centerville Rd	LC	Cable hardline and phone are touching	3 spans	235H	
50 2902 Condit St	LC	Newer pole, no anchor put in, down guy hanging from pole	Drops not properly secured at pole	264	
51 2931 Condit St	LC	Amplifier pushing against power down guy		235	
52 2947 Centerville Rd	LC	Drop not properly attached to pole		239D3	
53 2949 Condit St	LC	Not bonded to power ground		92C3	
54 2973 Centerville Rd	LC	Cable hardline and phone are touching	3 spans	235H	
55 2981 Condit St	LC	Broken down guy	Sharp end of guy wire not secured	264	
56 30 Demont Ave E	LC	Hardline cable not attached to pole properly		239D3	
57 3004 Centerville Rd	LC	Loose down guy		264	
58 3010 Centerville Rd	LC	Missing down guy		264	
59 3076 Edgerton St	LC	Drop drooping in trees	Abandoned?	Table 232-1	
60 602 County Road D E	LC	Broken down guy	Across Interstate Highway 694	264	
61 626 County Road D E	LC	Drop not properly attached to pole		239D3	
62 66 County Road B2	LC	Loose down guy		264	
63 Condit St and Nadeau Road	LC	Ground wire not properly attached to pole	SE Corner	239A	
64 Condit St and Nadeau Road	LC	Pole guard cracked and not properly attached to pole	SW corner	239D3	
65 Country Drive and Nadeau Road	LC	Pole guard cracked		239D3	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
66 County Rd C and Sylvan St	LC	Missing strand across County Rd C and missing down guy	1 pole east, cracked cable guard on pole	264	
67 Edgerton St (between Allen Ave & County Rd D)	LC	Cable hardline and phone less than 12 inches apart	Several spans	235H	
68 N45 00.811 W093.06.216	LC	Missing down guy		264	
69 1588 Eustis St	LD	Underground cable drop exposed above ground	All around Multiple Dwelling Unit	352	
70 1618 Eustis St	LD	Underground cable drop exposed above ground	All around Multiple Dwelling Unit	352	
71 1632 Carl St	LD	Pole guard not attached properly to pole		239D3	
72 1632 Carl St	LD	Underground cable drop exposed above ground	All around Multiple Dwelling Unit, pedestal not installed properly	352	
73 1662 Eustis St	LD	Loose down guy	Strands sticking out at anchor	264	
74 1662 Eustis St	LD	Power supply not locked	2 power supplies on the same pole. Neither is locked.	224B2c	
75 1769 Pleasant St	LD	Needs pole transfer		214	
76 1802 Malvern St	LD	Needs pole transfer		214	
77 1847 Pleasant St	LD	Abandoned drop on ground		214B	
78 1976 Eustis St	LD	Drop hanging low over neighbor's lot	(neighbor is 1972 Eustis)	Table 232-1	
79 2438 Summer St	LD	Power supply not locked		224B2c	
80 Eustis & Spring St	LD	Needs pole transfer		214	
81 Lauderdale	LD	All Multiple Dwelling units should be checked by Comcast for problems with pedestals, unburied drops, grounding, etc.			
82 Spring St & Walnut St	LD	Cable hardline and phone less than 12 inches apart	3 spans	235H	
83 2184 Oakwood DR	MV	Abandoned power supply	Remove power supply	214B	
84 2299 Jackson Dr	MV	Drop not properly attached to pole	Drops laying on ground	239D3	
85 2340 Highway 10	MV	Cable TV hardline and phone are less than 12" apart	2 Spans	235H	
86 2434 County Road I	MV	Cables not properly attached to building		820.24 & 820.44	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
87 2458 County Road I	MV	Drop and taps not grounded			250
88 2458 County Road I	MV	Incomplete installation, cable spool laying on ground		214	
89 2508 County Road I	MV	Hardline cable not attached to pole properly		239D3	
90 2516 County Road I	MV	Loose down guy		264	
91 5086 Brighton LN	MV	Loose down guy		264	
92 5551 St Michael St	MV	Sharing ground strap at house with phone	Strap not designed for 2 ground wires		250.70
93 5557 St Michael St	MV	Abandoned drop on ground		214B	
94 5618 St Michael St	MV	Loose ground at house			250
95 5619 St Michael St	MV	Ground not attached at pedestal		250	
96 7613 Woodlawn Dr	MV	Cables not properly attached to building			820.24 & 820.44
97 7615 Woodlawn Dr	MV	Cables not properly attached to building			820.24 & 820.44
98 7617 Woodlawn Dr	MV	Cables not properly attached to building			820.24 & 820.44
99 7617 Woodlawn Dr	MV	Drop not properly attached to pole		239D3	
100 7618 Edgewood Dr	MV	Aerial cable used for underground		Good engineering practices, maintenance	
101 7618 Edgewood Dr	MV	Cables not properly attached to building	Using power conduit for support		820.24 & 820.44
102 7618 Edgewood Dr	MV	Cables not properly attached to building			820.24 & 820.44
103 7618 Edgewood Dr	MV	Drop not buried	All Multiple Dwelling Units in this area need to be inspected, and repairs made,	352	
104 7618 Edgewood Dr	MV	Drop not properly attached to pole		239D3	
105 7618 Edgewood Dr	MV	Loose down guy, strands of strand exposed at anchor		264	
106 7619 Woodlawn Dr	MV	Cables not properly attached to building			820.24 & 820.44
107 7624 Edgewood Dr	MV	Broken lashing wire		214	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
108 7624 Edgewood Dr	MV	Drop not properly attached to pole	2 drops	239D3	
109 7640 Edgewood Dr	MV	Drop not buried	Pedestal cover not secure	352	
110 8281 Sunnyside Rd	MV	No bond to power		92C3	
111 8305 Sunnyside Rd	MV	Drop not properly attached to pole	Drop running through fence	239D3	
112 8372 Greenwood Dr	MV	Abandoned drop on ground		214B	
113 Bronson Dr @ St Stephen St	MV	Missing down guy		264	
114 Edgewood Dr & County Road I	MV	Missing down guy		264	
115 Edgewood DR & Woodlawn Dr	MV	Shrink boot missing one piece not shrunk		Good engineering practices, maintenance	
116 Highway 10 & Pleasantview Dr	MV	Power supply not locked		224B2c	
117 Long Lake Rd & County Road I	MV	Missing down guy	1 Pole south of intersection	264	
118 1359 27th Ave NW	NB	Pedestal doors are held closed with a wire		214	
119 1364 Long Lake Rd	NB	Missing down guy	Across Long Lake Rd	264	
120 1401 15th St NW	NB	Cable TV drop 12' 7" above road		Table 232-1	
121 1542 29th Ave NW	NB	Power supply not locked		224B2c	
122 1620 Old US Highway 8	NB	Missing down guy		264	
123 1647 Old US Highway 8	NB	Loose down guy	10 feet of excess strand is on the ground	264	
124 1845 Mississippi St	NB	Cable TV drops 14' 2" above road		Table 232-1	
125 1951 Long Lake Rd	NB	Hardline cable not attached to pole properly		239D3	
126 1975 Long Lake Rd	NB	Loose down guy	Hit by car recently (tracks still show in snow)	264	
127 2001 Long Lake Rd	NB	Hardline cable not attached to pole properly	Attached with tape	239D3	
128 2001 Long Lake Rd	NB	Loose down guy		264	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
129 2007 28th Ave NW	NB	Smashed pedestal		214	
130 2010 28th Ave NW	NB	Drop not buried		352	
131 2120 Long Lake Rd	NB	Missing down guy		264	
132 2130 Long Lake Rd	NB	Drop not properly attached to pole		239D3	
133 2180 Long Lake Rd	NB	Drop not properly attached to pole		239D3	
134 2180 Long Lake Rd	NB	Power supply not locked		224B2c	
135 2216 26th Ave NW	NB	Loose down guy		264	
136 2253 Leona Dr	NB	Drop not buried		352	
137 2253 Leona Dr	NB	Drop not grounded at house			820.100
138 2502 13th Terrace NW	NB	Smashed pedestal		214	
139 2509 14th St NW	NB	Drop not properly attached to pole	Hardline not properly attached to pole	239D3	
140 26th Ave NW & 22nd Terrace NW	NB	Drop not properly attached to pole, not buried at base of pole	Southwest corner	239D3	
141 26th Ave NW & 22nd Terrace NW	NB	Ground wire not properly attached to pole	Southeast corner	239A	
142 2746 13th Terrace NW	NB	Smashed pedestal		214	
143 2850 13th Terrace NW	NB	Drops not buried at pedestal		352	
144 2850 13th Terrace NW	NB	Pedestal doors are held closed with a bungee cord		214	
145 495 8th Ave NW	NB	Broken down guy, cable less than 40" from power		264	
146 604 10th St NW	NB	Loose down guy		264	
147 604 10th St NW	NB	Power supply not locked	2 power supplies on the same pole. Neither is locked.	224B2c	
148 630 Old Highway 8	NB	Broken down guy	N45 03.605 W093 11.766	264	
149 822 7th Ave NW	NB	Drop not properly attached to pole		239D3	
150 840 8th St NW	NB	Cable hardline and phone are touching		235H	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
151 928 7th Ave NW	NB	No bond to power's ground		92C3	
152 Mississippi St & Leona Dr	NB	Loose down guy		264	
153 N45 04.944 W093 13.404	NB	Power supply fuse box not locked		224B2c	
154 N45 05.015 W093 13.444	NB	Power supply and fuse box not locked, not bonded to power ground		224B2c	
155 N45 02.577 W093 11.918	NB	Loose down guy		264	
156 11 Pine Cone Rd	NO	New underground drop on top of ground	Bury in the Spring		
157 14 White Pine Rd	NO	New underground drop on top of ground	Bury in the Spring		
158 15 E Oaks St	NO	Cable and phone are less then 12 inches apart		235H	
159 18 Springfarm LN	NO	Drop not properly attached to pole		239D3	
160 2 chipmunk LN	NO	Broken lashing wire	Cable is 5 feet off ground (in wooded area)	214	
161 20 Summit Ridge Dr	NO	Drop not buried		352	
162 20 Summit Ridge Dr	NO	Wrong sized pedestal	Pedestal doesn't fit over tap	214	
163 22 E Oaks Rd	NO	Loose down guy		264	
164 22 Springfarm LN	NO	Loose down guy		264	
165 23 E Oaks St	NO	No bond to power and phone ground		92C3	
166 3 Goldfinch LN	NO	Ground wire not properly attached to house			250
167 32 W Pleasant Lake Rd	NO	Pedestal not properly closed		214	
168 4 Goldfinch LN	NO	Drop not buried	Pedestal not closed	352	
169 50 E Pleasant Lake Rd	NO	Broken lashing wire		214	
170 50 E Pleasant Lake Rd	NO	Drop drooping from strand to ground		Table 232.1	
171 50 E Pleasant Lake Rd	NO	Drop not buried		352	
172 51 E Pleasant Lake Rd	NO	Drops not buried at pedestal		352	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
173 68 Charles Lake Rd	NO	Amp pedestal is open	Reported to Comcast	214	
174 7 E Oaks St	NO	Cable and phone are touching		235H	
175 70 E Oaks Rd	NO	Power supply not locked		224B2c	
176 9 E Oaks St	NO	Missing down guy		264	
177 Black Oak Rd & Charles Lake Rd	NO	Amplifier pedestal smashed	Doors don't close properly	214	
178 Duck Pass Rd & Gadwell Ln	NO	Cable 13 feet 2 inches above road		Table 232-1	
179 Marsh Ridge Rd & East Oaks Rd	NO	Cable 14 feet 5 inches over Marsh Ridge Rd, phone tie wrapped to cable to gain clearance		Table 232-1	
180 N45 05.189 W093.03.446	NO	Power supply not locked		224B2c	
181 N45 05.189 W093.03.442	NO	Power supply ground not bonded to power's ground		99C	
182 N45 05.189 W093.03.497	NO	Missing down guy		264	
183 N45 05.219 W093.03.609	NO	Missing down guy		264	
184 N45 05.375 W093.03.803	NO	Missing down guy		264	
185 N45 05.409 W093.03.836	NO	Missing down guy		264	
186 N45 06.520 W093 05.414	NO	Loose down guy		264	
187 Oaks Road E & E Pleasant Lake Rd	NO	Power supply not locked		224B2c	
188 West Pleasant Lake Rd & White Oaks LN	NO	Power supply not locked	Doors were open	224B2c	
189 1064/1074 Roselawn Ave	RV	Missing down guy		264	
190 1362 Eldridge Ave	RV	Drop not properly attached to pole	Climbing hazard, frontyard	239D3	
191 1362 Eldridge Ave	RV	Missing down guy	Going east, backyard	264	
192 156 South McCarrons Blvd	RV	Hardline cable less then 9 feet 6 inches above lot		Table 232-1	
193 1619 Skillman Ave	RV	Cable hardline and phone are touching	2 spans - N45 00.206 W093 10.067	235H	
194 1715 Alta Vista Dr	RV	Drop not properly attached to pole		239D3	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
195 182 South McCarrons Blvd	RV	Loose down guy		264	
196 1821 Dale Ct	RV	Drop not properly attached to pole		239D3	
197 1822 Western Ave N	RV	Drop 6 feet above ground	Drooping through trees	Table 232-1	
198 1839 County Road B	RV	Power supply not locked		224B2c	
199 1871 County Road B	RV	Broken lashing wire		214	
200 1898 Gluek Ln	RV	Drop not buried		352	
201 1898 Gluek Ln	RV	Drop not properly attached to pole		239D3	
202 1906 Hythe St	RV	Drop not properly attached to pole	Drop tied to fence	239D3	
203 1967 Hamline Ave	RV	Drop not properly attached to pole	Climbing hazard	239D3	
204 1967 Hamline Ave	RV	No bond to power's ground		92C3	
205 2079 Roselawn Ave	RV	Power supply not locked		224B2c	
206 2085 Dellwood Ave	RV	Drop not properly attached to pole	Shrink wrap not shrunk	239D3	
207 210 South McCarrons Blvd	RV	Missing down guy	Across McCarrons Blvd	264	
208 2122 Cleveland Ave	RV	Drop not properly attached to pole		239D3	
209 2172 Ferris Ln	RV	Drop not buried	Multiple drops	352	
210 2172 Ferris Ln	RV	Drop not properly attached to pole	Multiple drops	239D3	
211 2185 Cleveland Ave	RV	Loose down guy	Abandoned cable laying on ground	264	
212 2211 Rosewood LN	RV	Ped too small to protect tap		214	
213 2235 Rosewood Ln N	RV	Smashed pedestal		214	
214 2579 Fairview Ave	RV	No bond to power's ground		92C3	
215 2579 Fairview Ave	RV	Power supply not locked		224B2c	
216 2951 Old Highway 8	RV	Drop not properly attached to pole		239D3	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
217 2951 Old Highway 8	RV	Power supply not locked		224B2c	
218 3003 Old Highway 8	RV	Broken down guy		264	
219 3037 Old Highway 8	RV	Power supply not locked		224B2c	
220 3090 Cleveland Ave	RV	Cable and phone are touching		235H	
221 3090 Cleveland Ave	RV	Power supply not locked		224B2c	
222 460 S McCarrons Blvd	RV	Cable hardline and phone are touching		235H	
223 542 Roselawn Ave W	RV	Drop not buried		352	
224 542 Roselawn Ave W	RV	Drop not properly attached to pole		239D3	
225 576 Roselawn Ave W	RV	Loose down guy		264	
226 N McCarrons Blvd& Western Ave	RV	Hardline 13 feet 9 inches above road		232-1	
227 N44 59.938 W093 10.776	RV	Power supply and fuse box not locked		224B2c	
228 N44 59.938 W93 09.952	RV	Loose down guy	New pole, drops not moved to new pole	264	
229 N44 59.976 W093 09.395	RV	Broken lashing wire	Across Hamline Ave	214	
230 N45 00.195 W093.09.318	RV	Loose down guy		264	
231 N45 00.211 W093.09.318	RV	Loose down guy		264	
232 N45 01.241 W093 07.578	RV	Power supply not locked		224B2c	
233 N45 02.145 W093.11.350	RV	Power supply not locked		224B2c	
234 Old Highway 8 & Brenner Ct	RV	Broken down guy		264	
235 S McCarrons Blvd& Woodruff Ave	RV	Cable hardline and phone are touching	Broken lashing wire	235H	
236 South McCarrons Blvd and Rice St	RV	Missing down guy		264	
237 2518 NE 33rd Ave	SA	Drop not properly attached to pole	Climbing hazard	239D3	
238 2554 37th Ave NE	SA	Power supply not locked		224B2c	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
239 2609 NE 34th Ave	SA	Drop not properly attached to pole	Climbing hazard	214	
240 2701 Silver Ln	SA	Cable TV hardline and phone are less than 12" apart		235H	
241 2705 Silver Ln	SA	Drop not properly attached to pole	Climbing hazard	239D3	
242 2816 NE 32nd Ave	SA	Drop not properly attached to pole		239D3	
243 2955 NE 34th Ave	SA	Broken down guy		264	
244 3012 33rd Ave NE	SA	Power supply not locked		224B2c	
245 3016 NE 33rd Ave	SA	Power supply and fuse box not locked		224B2c	
246 3101 Ne 29th Ave	SA	Drop hanging in trees		Table 232-1	
247 3104 NE Edward St	SA	Broken down guy		264	
248 33rd Ave NE & Rankin Rd	SA	Power supply not locked		224B2c	
249 3462 NE 31st Ave	SA	Broken down guy		264	
250 34th Ave & Belden Dr	SA	Broken lashing wire	2 spans	214	
251 3541 Silver Lake Rd	SA	Broken lashing wire		214	
252 3541 Silver Lake Rd	SA	Drop not properly attached to pole	Climbing hazard	239D3	
253 3605 NE 37th Ave	SA	Broken strand	At amp housing	264	
254 3800 NE MacAlaster Drive	SA	Broken lashing wire		214	
255 3800 NE Macalaster Drive	SA	Cable attached to power mast at house			820.44C
256 3800 NE MacAlaster Drive	SA	Hardline cable not attached to pole properly	Climbing hazard	239D3	
257 3800 NE MacAlaster Drive	SA	Loose down guy		264	
258 3800 NE MacAlaster Drive	SA	Underground cable drop exposed above ground		352	
259 4020 Silver Lake Terrace	SA	Cable TV 15' 1" above road		Table 232-1	
260 N45 01.666 W093 12.792	SA	Power supply fuse box not locked		224B2c	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

	Address	City	Issue	Comments	Codes	
					NESC	NEC
261	1025 Tomlyn Ave	SV	Bent pedestal	Doesn't close properly	214	
262	1219 County Rd I	SV	Broken down guy		264	
263	148 Demar Ave	SV	Drop attached to power mast			820.44C
264	148 Demar Ave	SV	Drop not properly attached to pole		239D3	
265	3360 Soo St	SV	Cable and phone are touching		235H	
266	3360 Soo St	SV	Missing down guy		264	
267	3402 Soo St	SV	Missing strand across street and missing down guy	N45.02.696, W093.06.595	264	
268	3409 Nancy Pl	SV	Drop not properly attached to pole		239D3	
269	3414 Soo St	SV	Loose down guy		264	
270	3518 Lexington Ave	SV	Broken ground wire, no bond to power		214	
271	3681 Rustic Pl	SV	Broken lashing wire		214	
272	3698 Kent St	SV	Amplifier pedestal knocked over		214	
273	3715 Victoria St	SV	Ground wire not attached to pole		239A	
274	3744 Rustic Pl	SV	Cable hardline and phone are touching		235H	
275	3788 Rustic Pl	SV	Drop not properly attached to pole		239D3	
276	4121 Victoria St	SV	Drop not properly attached to pole		239D3	
277	4188 Victoria St	SV	Broken ground wire on pole		214	
278	4188 Victoria St	SV	Cable guards not properly attached to pole			Good engineering practices, maintenance
279	4300 Rice St	SV	Broken down guy		264	
280	4666 Lexington Ave	SV	Broken down guy		264	
281	4722 Lexington Ave	SV	Drop not properly attached to pole		239D3	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

Address	City	Issue	Comments	Codes	
				NESC	NEC
282 4737 Hanson Rd	SV	Drop not properly attached to pole		239D3	
283 4861 Hanson Rd	SV	Drop not properly attached to pole		239D3	
284 5844 Hamline Ave	SV	Broken ground wire, no bond to power		214	
285 605 Ash St	SV	Missing pedestal cover	N45 07.447 W093.06.560	214	
286 645 Bucher Ave	SV	Drop not properly attached to pole		239D3	
287 900 Cannon Ave	SV	Broken down guy		264	
288 910 County Rd D W	SV	Loose down guy		264	
289 923 County Rd D W	SV	Drop not properly attached to pole		239D3	
290 938 County Road I	SV	Drop not properly attached to pole		239D3	
291 948 County Road I	SV	Power supply not locked		224B2c	
292 965 County Rd D W	SV	Ground wire cut at base of pole		250	
293 978 County Road I	SV	Power supply not locked		224B2c	
294 County Rd F & Victoria St	SV	Ground wire not attached to pole	No bond to power	239A	
295 Hamline & Highway 96	SV	Hardline cable not attached to pole properly		239D3	
296 Monterey Dr & Tanglewood Dr	SV	Loose down guy		264	
297 N45 03.487 W93.06.380	SV	Loose guy and missing down guy	Across Rice St	264	
298 N45 03.669 W93.06.380	SV	Broken down guy		264	
299 N45 03.774 W93.06.395	SV	Broken down guy		264	
300 N45 04.411 W93.06.388	SV	Drop looping through trees	Abandoned	Table 232-1	
301 N45 05.755 W093 07.631	SV	Power supply fuse box not locked		224B2c	
302 N45 07.143 W093 07.685	SV	Power supply not locked		224B2c	
303 Nelson Dr & Lexington Ave	SV	Power supply not locked		224B2c	

## Attachment A - NSCC Comcast Physical Plant Audit Issues

	Address	City	Issue	Comments	Codes	
					NESC	NEC
304	Rice St & Rustic Pl	SV	Loose guy and down guy	Across Rice St	264	
305	Rice St & Ste Marie St	SV	Loose down guy		264	